

Parts Manufacturer Approval

Parts Manufacturer Approval Information

Supplement Number:
194

Supplement Date:
11/07/2007

This approval issued to:
Univair Aircraft Corp

PMA Holder Number:
PQ0012NM

PMA Holder's Address:
2500 Himalaya Rd
Aurora CO 80011-8156
United States

Part Name:
Valve Assembly

Part Number:
U4500A-1

Replacement For:
Scott 4200-A1 4500-A1
Piper 492 023

Make/Model:
Piper (PA-18, PA-18S , PA-18 105 , (Special) , PA-18S 105 , (Special) , PA-18A , PA-18 125, (Army L-21A) , PA-18S 125 , PA-18AS 125 , PA-18 135, (Army L-21B) , PA-18A 135 , PA-18S 135 , PA-18AS 135 , PA-18 150 , PA-18A 150 , PA-18S 150 , PA-18AS 150 , PA-19 , (Army L-18C) , PA-19S, PA-18A, (Restricted) , PA-18A 135 , (Restricted), PA-18A 150 , (Restricted), PA-22, PA-22-108 , PA-22-135 , PA-22S-135 , PA-22-150 , PA-22S-150 , PA-22-160 , PA-22S-160)
Univair Aircraft Corp (108, 108-1, 108-2, 108-3)

FAA Approval Basis:
Test and Computation per 14 CFR § 21.303 DWG No: U4500A Rev: None Date: 5.8.07 or later FAA approved revisions

Responsible Office:
Los Angeles FAA Office Tel: (562) 627-5290

Additional Information: